

From: [Galinsky, Virginia](#)
To: [Marcus, Danny](#)
Subject: Meyer Drum Reclamation furnace afterburner testing.
Date: Wednesday, August 21, 2013 4:06:59 PM
Attachments: [20130821154515157.pdf](#)

This testing was done before the facility installed a permanent total enclosure around the drum furnace, but I believe it is the only testing they have done on it.

Virginia (Palmer) Galinsky
Environmental Engineer
Air Enforcement & Compliance Assurance Branch
U.S. EPA, Region 5
Phone: (312) 353-2089
Fax: (312) 697-2711
galinsky.virginia@epa.gov

-----Original Message-----

From: R5-17-18@epa.gov [<mailto:R5-17-18@epa.gov>]
Sent: Wednesday, August 21, 2013 2:45 PM
To: Galinsky, Virginia
Subject: Message from "R5-17-18"

This E-mail was sent from "R5-17-18" (Aficio MP 6001).

Scan Date: 08.21.2013 15:45:14 (-0400)
Queries to: R5-17-18@epa.gov